

**TP94693 FELT WICK AND
TP111410 FLAT WASHER**

APPARATUS AFFECTED: 1B and 2B Tape Reperforator — Dataspeed, TP146178 Modification Kit, Improved Design Parts.

OBJECT: To facilitate manufacture and to revise bulletin information to represent actual assembly procedures.

CHANGE: (1) Teletype Bulletin 1154B, page 1-6, change 7 rear plate assembly.

- (A) The TP156948 felt wick has been replaced by a TP94693 felt wick.
The TP156948 wick has a diameter of 1/16 inch and an over-all length of 5/32 inch.
The TP94693 wick has a diameter of 1/8 inch and an over-all length of 19/64 inch.

(2) Teletype Bulletin 1154B, page 1-10, change 7 main shaft assembly.

- (A) The TP104807 spacer has been replaced by a TP111410 flat washer.
- (B) A TP111410 flat washer has been added to the assembly and will be located between the TP151637 screw (applies only to upper assembly. Lower assembly of screw does not use a flat washer under the screw head.) and the TP143072 bearing shield.
- (C) The TP110434 flat washer (incorrect part number shown), located between the TP142806 bearing shield and the TP110743 lockwasher, has been eliminated.

IDENTIFICATION: See "CHANGE".

INTERCHANGEABILITY: Not affected.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: The changes are now in effect.

W.E.CO. STOCK OF OLD STYLE PARTS: May be furnished.

APPLICATION TO APPARATUS IN THE FIELD: Old style parts giving satisfactory service need not be replaced.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: Units may be equipped with new or old style parts.

AVAILABILITY: New style parts are available.