

Teletype Corporation
Chicago, Illinois, U.S.A.

764EE
Issue 1
November, 1951

CHANGES AND ADDITIONS TO
BULLETINS 1108 (ISSUE 2) - PAGE 7 AND
1126 (ISSUE 1) - PAGE 2 MODEL 14 REPERFORATOR TRANSMITTERS

The 102381 platen support has been replaced by a 123199 platen support which differs in that it accommodates a 111603 polyvinyl alcohol platen. The 111603 platen replaces the 102380 platen (with 103538 insert).

New and old style parts are not individually interchangeable. However, these parts are interchangeable in pairs.

*

*

*