

CHANGE AND ADDITION TO BULLETINS

1038	Issue 2	1089	Issue 1	1117	Issue 2
1067	Issue 2	1090	Issue 2	1126	Issue 1
1080	Issue 1	1093	Issue 1	1130	Issue 1
1082	Issue 2	1100	Issue 2	1132	Issue 1
1088	Issue 2	1108	Issue 2		

The 73481 tape tension lever has been replaced by a 121995 tape tension lever of improved design, which is provided with a $1/4$ " wide flat surface to serve as a finger hold as indicated on the sketch below.

New and old style tape tension levers are interchangeable.

