

CHANGES AND ADDITIONS
TO THE FOLLOWING PARTS BULLETINS

BULLETIN NO. 1080B, ISSUE 1, PAGE 5
BULLETIN NO. 1064B, ISSUE 2, (BELL) PAGE 5
SINGLE MAGNET REPERFORATOR (RPE)
(MODELS 14 AND 20 NON-TYPING)
BULLETIN NO. 1052B, ISSUE 1, PAGES 2 AND 3
(SIX-UNIT PERFORATOR (MPE)

To provide a means for identifying the beginning or the end of a fully perforated six-unit tape the 81603 tape knife has been replaced by a 123581 tape knife. The 123581 tape knife cuts a triangular notch which produces a small flag on the trailing edge of the tape as it is torn off, and a corresponding notch on the leading edge.

NOTE: Part No. 87603 referred to in Bulletin No. 1064B is in error. This number should be 81603.

* * *