

ADDITION AND CORRECTION  
TO BULLETIN 138, ISSUE 5,  
ADJUSTMENTS TYPE BAR PAGE PRINTER MODEL 15

This correction sheet is being reissued to correct an omission in Issue 1 of EE-508. Disregard the information found in Issue 1 and substitute the following:

PAGE 59

Omit the NOTE under "LEFT PRESSURE ROLLER LEVER SPRING TORSION" and add it under "RIGHT PRESSURE ROLLER LEVER SPRING TORSION."

Under "LEFT PRESSURE ROLLER LEVER SPRING TORSION" add the following statement: "To adjust, loosen the mounting screw which mounts the left pressure roller spring bracket to the platen bracket casting, and rotate the spring bracket. Tighten the mounting screw."