

Teletype Corporation
Chicago, Illinois, U.S.A.

EE-533
Issue 1
January, 1946

CHANGES AND ADDITIONS
BULLETIN NO. 1064 (ISSUE 2)
PARTS - SINGLE MAGNET REPERFORATOR
(Model 14 and 20 Nontyping)

This correction sheet covers ordering information for the C182 cover (assem.) - gray wrinkle, which is the same as the C81 (84968) cover (assem.) - walnut (Bell System 14A) shown on page 8 of the bulletin except for the finish.

The four screw heads (two at each hinge) shown at the top of the cover door are incorrectly shown and should not be visible, as they are welded to the inside of the cover. The washers, lock washers, and nuts used with these screws may be ordered as 103-27 washers, 3640 lock washer, and 34-66 nuts.

The spring, used on the hinge to keep the door closed, may be ordered as 74637 spring.